

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Client ID: 80008KN0703

Work Order Name: WO/80008KN0703/1
Work Order Type: Weatherization

Audit Name: 80008KN0703-AUDIT

CLIENT INFORMATION

Client Name: Address:

Alt. Client ID: KNOX

<u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Agency Phone: (865) 244-3080

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1960

An EPA Certified Firm/Renovator is required.

Measures

Measure	1 Cr	awl Space Door			Componen	ts			Inspected
Comment	unit. A not pro homed Stand given	ve old door before installing a door is inclusive of pad loo essure treated, then paint(1 owner or sand/stain/seal), N ards for Weatherization Mar to home owner not anyone ed, the pad locks to be keye	k, hinges st quality lo change terials and else. If m	, hasp, semig es allov d Soutl ore tha	pressure tr loss color to red. Refer to neast Field (eated jam be chose Appendi Juide. All	bs, if on by x A-	•	
					Estimated			Actual	
# Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors		Floor or Crawl Space Door	Each	1					777
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
Labor		Labor	Each	1					77741
Other Detail									
***								L	
	·nu								
			1	Measure	Sub Total:		5	Sub Total:	
Field Note	s:						1704		

Measur	e 2 Do	or Jamb (Each Piece) d1			Componen	ts			Inspected
Commen	one so exterio	re old door jamb before ins lid piece. Door Jamb must r semigloss paint or stained dix A- Standards for Weath	be caulked/sealed	ed and to mat	painted with ch existing tr	1st qua im. Ref	ality er to		
					Estimated			Actual	
# Material	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors		Door Jamb & Door Shoe (Each Piece)	Each	1		*******			
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor		Labor	Each	1					
Other Deta	ii								

			ł	Measur	e Sub Total:			Sub Total:	
Field Not	es:				***************************************				

Report Run On: 5/8/2010

Measur	e 3 Infil	tration Redctn			Componen	its		Inspected
Commer	AND SE Type^In Living F Living F Bdrm1S Kitchen Dining F Bdrm2S •Reduce It is the perform A house ORDER "Open" 50 PA	EN RING GENRAL CAU EAL 8 SUPPLIES AND T itial (Pa) RoomSupply5.7 RoomSupply5.1 Room#2Supply4 Supply1.6 Supply3.4 RoomSupply Supply3.1 Supply4.2 e air infiltration with 10 air responsibility of the conted with a Blower Door. Community and the second of the content of the conte	ir seals. E ractor to fil contractor (low 1500 c argeted #. CFM @ 50	ach ai nd the must n sfm @ pasca	r seal is equ air leaks. Th neet or exce 50 pascals. Is. Target is	al to 100 nis is best ed the tar No CHAN 2750 CI	cfms. geted #. IGE	
	Seal all	plumbing penetrations.F	Replaceme	nt win	dow needed <i>Estimated</i>		Actual	
# Material	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty Unit Co.	st Total
1 Miscella	aneous Su	Infiltration Reduction	Each	10				
2 Labor		labor	Each	10				
Other Deta	n#							
				Measure	Sub Total:		Sub Total:	
Field No	des:			~~				

Page 4 of 13

Report Run On: 5/8/2010

Measure 4 DV	VH Pipe Insulation			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			[
		1	Measui	e Sub Total:			Sub Total:	
Field Notes:								

								ŀ

Page 5 of 13

Measur	e 5 Flo	or Ins. R-19			Componen	ts F-1			Inspected
Commen	before Standa subfloc (e.g. st compre	es labor cost. Contractor's installing insulation. Contrards. Insulation is installed or above (paper side again aves for blankets). Insulations. Refer to Appendicutheast Field Guide.	actor to in I to mainta est subfloc tion to ha	nstall u ain per or) inclu ve NO	sing Resnet manent cont iding necess gaps, voids,	Grade 1 act with the sary support	the orts		
					Estimated	· · · · · · · · · · · · · · · · · · ·		Actual	
# Material	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	on	Floor Insulation - Fiberglass Batts - R-19	SqFt	1221		~			
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	1221					
Other Deta	nil		_						
						7			
				Measur	e Sub Total:		S	Sub Total:	
Field Not	es:			******		***************************************			

	Measure 6 DWH	l Tank Insulation			Componen	ts			Inspected
C	omment extend p	ressure relief pipe as ne	eded		•				
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
C	ther Detail								
	**************************************								TAIL.
				Measur	e Sub Total:		;	Sub Total:	
	Field Notes:	774	,,	****		<u> </u>			
L									-

	Measure 7 In	stall/Replace Heatpump			Componen	ts H-1,A	C-1		Inspected
C	Must Aman Housi 2.0 to therm Thern	des labor cost. Must be insta perform an ACCA Manual J a or Goodman 13 Seer Spli ng Director for approval), 10 on. Final size will be determi ostat. Must be equal to Hon nostat (must submit equivale te client on operation of the	and subn t Heat Pu) KW eme ned by th eywell's F ent to Hou	nit witl mp (m ergenc e ACC PRO 4	n invoice. Mu nust submit e by heat. Size CA Manual J. 000 Program	ist be equivalent is approx Install imable	ial to to imately	ý	
#	Allada vial () at	B 141 15			Estimated			Actual	****
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipm	en Heatpump - 52 kBtu/h Existing, Consult Manual J Data	Each	1					
2	Labor	Heatpump - 52 kBtu/h Existing, Consult Manual J Data	Each	1					
C	ther Detail								
L									
				/leasur	e Sub Total:			Sub Total:	
	Fleld Notes:		701	100041	10 Aug.				

Page 8 of 13

Measure	8 Atti	ic Ins. R-38			Componen	ts A-1,	\-2		Inspected
Commen	attic sp access soffit ar insulati silicone access Grade	es labor cost. Contractor to ace showing depth of instance showing depth of instance as needed and covering vent. Seal allong. Seal around chimney or fire resistant foam. In and weather strip with foal 1 Standards. Refer to Appuls and Southeast Field Gulls.	ulation. Bu to preven holes, ga with shee stall R-30 am tape. Coendix A-3	ild ins it loos ps, an it meta fiberg Contra	ulation dam a e fill insulation d penetration al and high te lass batt sec ctor to install	around an from end and in attinger attention and in attinger attention and in attention and	attic entering c before ure attic tesnet)	
					Estimated			Actual	
# Material	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	n	Attic Insulation - Blown Fiberglass - R-38	SqFt	567		17.00			
2 Labor		Attic Insulation - Blown Fiberglass - R-38	SqFt	567					
3 Insulatio	n	Attic Insulation - Blown Fiberglass - R-38	SqFt	660					
4 Labor		Attic Insulation - Blown Fiberglass - R-38	SqFt	660		**************************************			
Other Deta	1			,	1	7,712,5114			
				L					
			ı	Measur	e Sub Total:		;	Sub Total:	
Field Note	es:								

Client ID: 80008KN0703
Alt. Client ID: KNOX

Work Order Name: WO/80008KN0703/1 Report Run On: 5/8/2010

Version 8.6.0 Page 9 of 13

1	Measure 9 CO	Monitor is Needed			Componen	ts			Inspected
С	comment Refer to Field Gu	Attachment A- Standardside.	s for Wea	theriza	ation Materia	ls and So	outheas	st	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							,
2	Labor	Labor	Each	1					
c	ther Detail								
						7/1			
				Measur	e Sub Total:			Sub Total:	
	Field Notes:							·	

Page 10 of 13

	Measure 10 Fix I	mproper Venting (Clothe	s Dryer)	Component	ts			Inspected
C	protrudii is 15 fee	ents installed with damper ng through pipe. Must be v et. No changes allowed. R rization Materials and Sou	ented to Refer to A	outsic Attachn	talled withou le of home. Nent A- Stand	t any fas ⁄/aximum	lenath	ì	-
				****	Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	ther Detail								
				Measur	Sub Total:			Sub Total:	
	Field Notes:		***************************************		- VAN			-	170.0

Report Run On: 5/8/2010

Measure 11 Fix ven	Ventilation Inadequate	(Attic) 2 lo	ow	Componen	ts	, , , , , , , , , , , , , , , , , , ,	***************************************	Inspected
of 1/15 change	ents installed on low par 0 of the area of space b s allowed. Refer to Attac lls and Southeast Field 0	eing ventila chment A- S	ated.1/	2 high and 1	/2 low. N	o o		
NOTE:	Do not install roof vents	on front pa	irt of h					
# Material / Labor	Description / Comment	13-14-		Estimated			Actual	
	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety 	Roof Vents Location	Each	2					
2 Labor	Labor	Each	2					
Other Detail								
			Measur	Sub Total:			Sub Total:	77011
	Water Leaks (Basemen		-	=	śs		I Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
		Λ	/leasure	Sub Total:		s	ub Total:	
Field Notes:				L			L	

Client ID: 80008KN0703 Alt. Client ID: KNOX Work Order Name: WO/80008KN0703/1 Report Run On: 5/8/2010

Page 12 of 13

		ctice Lead Safe Weathe or jamb)	rization		Componer	nts			Inspected
C	omment A Certif submit o activity.	ied Firm /Renovator is re copy of Lead Report and	quired to a d 3 pictures	adhere s (befo	to EPA RR ore, during, a	P rules. and after)	Need to of eac	o h	
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	EPA RRP Lead Rules	Each	1		77.			
2	Labor	Labor	Each	1					
<u>C</u>	ther Detail								
L									
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:		77.4	T-(H				7/1	
İ									
									-
L									~
٨	neasure 14 Vapo	or Barrier Needed 1221	sa ft		Componen	fe			nspected
	walls and earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea ization Materials and So	securely t ms. Refer	fastene to Atta	ed. Must be schment A- S	cleated d	own to	l	
11	•• • • • • •								
7	Matarial (Labou				Estimated			Actual	
	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Description / Comment Basement /Crawlspace Vapor Barrier	<i>Units</i> SqFt	Qty 1221		Total	Qty	***	Total
		Basement /Crawlspace		_		Total	Qty	***	Total
2	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1221		Total	Qty	***	Total
2	Health and Safety Labor	Basement /Crawlspace Vapor Barrier	SqFt	1221		Total	Qty	***	Total
2	Health and Safety Labor	Basement /Crawlspace Vapor Barrier	SqFt	1221		Total	Qty	***	Total
2	Health and Safety Labor	Basement /Crawlspace Vapor Barrier	SqFt SqFt	1221		Total		***	Total
2 0 (Health and Safety Labor	Basement /Crawlspace Vapor Barrier	SqFt SqFt	1221	Unit Cost	Total		Unit Cost	Total

Client Name:

Client ID: 80008KN0703
Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0703/1 Report Run On: 5/8/2010 DOE Weatherization Assistant

Version 8.6.0

Page 13 of 13